

Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Containment Boom being utilized at the perimeter of Zone 1



Crude Oil on Water Surface in Zone 1



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Crude Oil along Embankment of Trenasse in Zone 1



Far Reach of Impacted Trenasse in Zone 1 Illustrating Extent of Contamination



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Utilizing Wash Pumps to Flush the Area of Crude Oil in Zone 1



Utilization of Absorbent Pads for Crude Oil Removal in Zone 1



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Utilization of Absorbent Boom for Crude Oil Removal in Zone 1



Oil Samples taken by USCG MSU, Baton Rouge



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Oil Samples being packaged by USCG MSU, Baton Rouge



Emulsification and Crude Oil on Water Surface in Zone 3



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Waxy Paraffin in the water in Zone 4



Crude Oil and Emulsification on the Water Surface in Zone 4




Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Crude Oil on Water Surface in Zone 4



Sample taken at Zone 4 by USCG MSU – Baton Rouge



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Zone 3 – Impacted Vegetation



Zone 4 - Waxy Paraffin in the water



Bayou Sorrel Oil and Gas, LLC
Bayou Sorrel Field Production Facility Incident
Bayou Sorrel, Louisiana
October 2, 2007

Zone 5 – Emulsification



Zone 4 – Scare Cannon Operations

